

Highways update

Reported issues from previous Planning & Highways Committee meetings not yet dealt with

None

Issues raised at May meeting are as follows:

- 1) Haslemere: The road just beyond Holdfast Cottage, Holdfast Lane (heading toward Grayswood) is almost permanently covered in water which hides some pot holes – reported 1235435 – the area has been recommended for patching. Awaiting confirmation that the recommendation will be proceeded with
- 2) Wey Hill: Drivers of St Christophers Road are using the one-way entrance as an exit and there is concern about the danger to other road users – reported 1235436 - this has passed to Alex Pringle at SCC as this is a safety issue
- 3) Wey-Hill: There are water leaks north of Fosters Bridge (heading towards Shahanaz) Already reported to Thames Water reference 31288865.
- 4) March meeting - Broken bollard on Headley Road – reported 1181209 – (see item 2 below under jobs raised by SCC for our information to pass on). Conversation with SCC - Stuart Copping of SCC is going to replace the bollard. Under the terms of their contract Kier wouldn't replace it as it had been badly damaged and couldn't be reused.
- 5) April meeting - Haslemere: Grit bin at the junction of A287 and Polecat Hill has been driven into. It was in the road and has now been moved but is still slightly on the road. The grit bin has sustained damage – reported 1201705 - We have noted the damage to the gritting facility and will look at replacing it with a new one towards the end of the summer, in line with our annual programme of grit bin maintenance. If you believe the bin is causing an immediate hazard to road users, we ask that you raise this with Surrey County Council using the emergency contact number

Jobs raised by SCC for our information to pass on

- 1) Road name: Lion Lane
Location: Outside Shottermill Junior School
Job description: Removal of 'New Road Layout ahead' sign and adjust parking restriction sign
- 2) Road name: Headley Road
Location: Adjacent to second build-out (just past Rozeldene)
Job description: removal of post from footway, dispose and fill hole with concrete (see item 4 above from March meeting – broken bollard on Headley Road)
- 3) Road name: Park Road
Location: Verge outside 'Crofton'
Job description: Backfill hole in verge with hardcore/crushed concrete and top with 150mm of soil and seed.

- 4) Road name: Lion Lane
Location: From Shottermill Junior School to 31 Lion Lane
Job description: Footway is going to be repaired

- 5) Road name: Tilford Road
Location: Bus stop between junction of Churt Road and Beacon Crescent
Job description: Cut back and trim vegetation around bus stop and approaches

- 6) Road name: Tilford Road
Location: Junction with Churt Wynde
Job description: Cut back vegetation around speed terminal, back toward junction with Beacon Hill road, around playground sign and build outs

- 7) Road name: Weydown Road
Location: Outside Wychwood
Job description: Replacement of parking restriction sign

- 8) Road name: Whitmore Vale Road
Location: Outside Stream Farm, around bridge over stream
Job description: clear build-up of silt and gravel around bridge and approaches and clear D-channel to improve drainage

- 9) Road name: Vicarage Lane
Location: Footway between sub station and car park at the far end
Job description: cut back vegetation back to fence along footway and trim low hanging branches to full height (2.4m)

- 10) Road name: Townpath - Lion Lane to Woodlands Lane
Location: Entire length
Job description: cut back vegetation along path